



Facilities Notice

Capital Development & Delivery | Facilities Management
Saunders Building, PO Box 1700 STN CSC Victoria BC V8W 2Y2 Canada
T 250-721-7591 | www.uvic.ca/fmgt

Title:	Business & Economics Building - water reconnection
Location:	Business & Economics Building (Building #217)
Description:	Facilities Management and Aral Construction are completing repairs to the incoming water piping to the building. The flushing procedure may cause <i>turbidity</i> in the pipes, lifting old deposits and sediments. Water is safe for use, and these changes are aesthetic and do not pose a health hazard. We apologize for any concerns or inconvenience this may cause and hope any noted changes clear up quickly with use.
What You May Observe:	
<ul style="list-style-type: none">• Air in Lines: Water <i>may</i> appear milky or bubbly because of trapped air; this will clear with time and use.• Cloudy or Discolored Water: Water <i>may</i> appear brown, or yellowish, due to naturally occurring mineral deposits (iron and manganese) being disturbed during flushing.• Taste or Odor Changes: Slight metallic or earthy taste <i>may</i> occur temporarily.• Sediment in Water: Small particles <i>may</i> be visible, especially after periods of inactivity.	
Time frame:	December 18th – January 2nd
FMGT contact:	Cort Zawalek, Project Manager
Email address:	cortzawalek@uvic.ca
Phone:	(250) 514-1365