



Facilities Notice

Capital Development & Delivery | Facilities Management
Saunders Building, PO Box 1700 STN CSC Victoria BC V8W 2Y2 Canada
T 250-721-7591 | www.uvic.ca/fmgt

Title: Heating Loop 501 Replacement

Location: BWC B Wing – Rooftop

Description: Facilities Management and Aral Construction are replacing heating loop 501 and associated infrastructure. The air handling unit, serving the **fume hoods on Levels 1 – 4 in B-wing only**, will be switched to an alternative air handling unit for the duration of the work. Building occupants should not notice any change to air flow. If air flow changes are noticed please contact Jason Minard at FMGT. Contact information below.

We apologize for any inconvenience.

Time frame: January 20 - 31, 2026

FMGT contact: Jason Minard, Project Manager

Email address: jminard@uvic.ca

Phone: 236 638 3942