

TREASURY AND RISK MANAGEMENT

Michael Williams Building

PO Box 1700 STN CSC Victoria BC V8W 2Y2 Canada

Title:	Clearihue B Wing Basement – Washroom Restoration
Location:	Hallway B001A, Washroom B002, Washroom B004, Circulation Space B001B, Mechanical space B005, Custodial Space B003, and basement entry doors at the bottom of B Wing Stairwell # 3 into 0 level
Description:	<p>The Office of Treasury & Risk Management are managing an insurance claim in the Clearihue basement between A and B wings. Downs Construction Ltd. have been engaged to remedy a plumbing issue that occurred in restroom B004.</p> <p>The general repairs to the drywall will take up to three weeks, with full repairs to Washrooms B002 & B004 taking approximately 2 months.</p> <p>Please reach out to Stephanie Smith with any questions or concerns.</p>
Time frame:	<p>General Repairs: Tuesday, January 29, 2025 – Friday, February 21, 2025</p> <p><i>Video Conference room B007 will not be impacted, but will be out of service for bookings during this time.</i></p> <p>Restrooms Repairs: Tuesday, January 29, 2025 – Friday, March 28, 2025</p>
RISK contact:	Stephanie Smith, Risk and Insurance Analyst
Email address:	riskanalyst@uvic.ca
Phone:	250-853-3100