

FACILITIES MANAGEMENT

Saunders Building

PO Box 1700 STN CSC Victoria BC V8W 2Y2 Canada

Title: Sedgewick Window Replacement

Location: Impacted rooms in the Sedgewick Buildings include:

- C116 office
- C118 office
- C120 office
- B125 board room

Description: Island EHS Ltd. are undertaking a survey in the Sedgewick building rooms listed above to ascertain if there are hazardous materials present prior to window replacement at a future date. In support of this work, Island EHS would require this room to be vacant during the survey period. It would take place 10:00AM to 1:00PM on Thursday, April 3, 2025.

Please reach out to me (Holister Ogah) with any questions or concerns.

Time frame: Thursday, April 3rd, 2025, at 10:00 am to 1:00 pm

FMGT contact: Holister Ogah, Project Manager

Email address: hogah@uvic.ca

Phone: 250-880-0215

